



# SMS LABS SERVICES PRIVATE LIMITED

## TEST REPORT



TC-6118

2021 - 0012-83 / 21/5/2021  
1770/

Report No : EN21050040-01

Page 1 of 1

Report Date: 20 May 2021

Customer Name : M/s. Asian Paints Limited. (Penta Division)  
Customer Address : B5-B10, SIPCOT Industrial Complex, Kudikadu, Cuddalore - 607005.  
Sample Name : Air  
Sample Description : Ambient VOC Monitoring  
Reference : Test Request Form Dated 13.05.2021  
Sample Drawn By : Laboratory  
Sample Location : AAQ Station  
Sample Procedure : SMSLA/EN/SOP/034  
Relative Humidity : 59%  
Sampling Date : 13 May 2021  
Sample Received on : 17 May 2021  
Test Started on : 17 May 2021  
Test Completed on : 19 May 2021  
Ambient Temperature : 32°C

### TEST RESULTS

S.NO	Parameter	Test Method	Results	Unit	Limit as per NAAQS Specification
<b>Chemical</b>					
1	Carbon Monoxide as CO (8hrs)	IS 5182 (Part 10 )	BLQ(LOQ:1.14)	mg/m <sup>3</sup>	02 Max.
<b>Others - Hydrocarbons</b>					
2	Total Hydrocarbons	SMSLA/GM/SOP/08	BLQ(LOQ:100.0)	µg/m <sup>3</sup>	--

Note : BLQ Below Quantification Limit, LOQ Limit of Quantification

Conclusion : The above tested sample complies the NAAQ standards for the above tested parameters

/\*\*\*\*\* End of the Report \*\*\*\*\*/

A. Manikandan  
Authorized Signatory - Chemical

Laboratory Address : 39/6, Thiruvallur High Road , Puduchatram Post, Thirumazhisai Via, Poonamallee Taluk, Chennai 600 124.

Laboratory - Accredited By : NABL (TC-6118) ; Approved By : BIS ; Recognized By : APEDA, MoEF, FSSAI, AGMARK; Certified By : ISO 9001 & OHSAS 18001.

- ★ The results relate only to the items tested.
- ★ Reports shall not be reproduced except in full without the approval of the Laboratory.
- ★ The laboratory's responsibility under this report is limited to proven wilful negligence and will in no case be more than the invoiced amount. The Laboratory accepts no liability with regard to the origin or source from which the sample(s) is / are said to be extracted.