— ENVIRO-INTERNATIONAL —

NABL, UPPCB-HO/600/CC/89/2009-10/2023 & ISO : 9001 : 2015, ISO : 14001 : 2015,
ISO : 45001 : 2018 Certified Environmental Laboratory
PAN: AAAFE9844N | GSTIN: 09AAAFE9844N1ZT

27 YEARS SERVICES

TEST REPORT

ISSUED TO: **M/s. ASIAN PAINTS LIMITED.** A1B2, UPSIDC INDUSTRIAL AREA, KASNA VILLAGE, Gr. NOIDA, G.B. NAGAR – 203207 (UP) INDIA,	SUBJECT : AMBIENT AIR QUALITY MONITORING METHODS : Based on CPCB Methods /NAAQ-18.11.09 Gazette Notifications INSTRUMENTS: RDS/FPS/COMBO, GC. AAS, Spectrophotometer
Sample Details : AAQ Sample Reference: EIL/API./10/26/AAQ: 1-6	Sample Collection Date: 07 & 08/10/26 Sample Reporting Date: 14/10/26

WEEK – I

SAMPLING SITE	UNIT	NEAR Gate No. 02	Near ETP Area	NEAR RMG Area	NEAR Gate no.02	Near ETP Area	NEAR RMG Area	Stds* Annual NAAQ
Sampling Code	--	AAQ – 1	AAQ – 2	AAQ – 3	AAQ – 4	AAQ – 5	AAQ – 6	--
Sampling Date	--	07/10/26 TO 08/10/26	07/10/26 TO 08/10/26	07/10/26 TO 08/10/26	08/10/26 TO 09/10/26	08/10/26 TO 09/10/26	08/10/26 TO 09/10/26	--
Sampling Duration	--	24 Hours	24 Hours	24 Hours	24 Hours	24 Hours	24 Hours	--
Product	--	Paint	Paint	Paint	Paint	Paint	Paint	--
Average Operating Hours	--	3 Shift	3 Shift	3 Shift	3 Shift	3 Shift	3 Shift	--
Weather	--	Normal	Normal	Normal	Normal	Normal	Normal	--
Wind Direction	--	W – E	W – E	W – E	W – E	W – E	W – E	--
Ambient Temperature	°K	303	303	303	303	303	303	--
Particulate Matters <PM10	µg/m³	246	244	227	253	239	262	< 60
Particulate Matters <PM2.5	µg/m³	156	158	150	137	148	140	< 40
Sulphur Di Oxide (SO2)	µg/m³	32	42	38	29	35	31	< 50
Nitrogen Di Oxide (NO2)	µg/m³	26	24	32	23	29	20	<40
Ozone as O3	µg/m³	08	13	07	11	14	16	< 100**
Lead as Pb	µg/m³	BDL	BDL	BDL	BDL	BDL	BDL	< 0.5
Carbon Monoxide as CO	mg/m³	<1	<1	<1	<1	<1	<1	< 2**
Ammonia as NH3	µg/m³	09	11	05	07	08	06	<100
Benzene as C6H6	µg/m³	BDL	BDL	BDL	BDL	BDL	BDL	< 05
Benzeno (a)Pyrene	ng/m³	BDL	BDL	BDL	BDL	BDL	BDL	< 01
Arsenic as As	ng/m³	BDL	BDL	BDL	BDL	BDL	BDL	<06
Nickel as Ni	ng/m³	BDL	BDL	BDL	BDL	BDL	BDL	<20

*EPR-1986/ Schedule VII/NAAQ/Page561/ Annual.** 8 Hours. BDL. <0.25,

Checked By

R.P. Marwah

EIL/Lab-In-Charge

Dr. Vipul Kumar

Greater Noida

N.B.:-

- The Sample/Samples received shall be destroyed after 2 weeks unless specified otherwise.
- The Result indicated only refer to the tested samples.
- The Certificate shall not be used in any media or as evidence in the court of law.

Off. & Lab :138-139, Udyog Kendra-II Extn, Eco Tech-III, Greater Noida-201 306
:9810098664, 9810725666, 9910233668
:vipul_kumar4@rediffmail.com | environternationalec@gmail.com

ISO/IEC-17021 CB

— ENVIRO-INTERNATIONAL —

NABL, UPPCB-HO/600/CC/89/2009-10/2023 & ISO : 9001 : 2015, ISO : 14001 : 2015,
ISO : 45001 : 2018 Certified Environmental Laboratory
PAN: AAAFE9844N | GSTIN: 09AAAFE9844N1ZT

TEST REPORT

ISSUED TO: M/s. ASIAN PAINTS LIMITED. A1B2, UPSIDC INDUSTRIAL AREA, KASNA VILLAGE, GT. NOIDA, G.B. NAGAR - 203207 (UP) INDIA,	SUBJECT : AMBIENT AIR QUALITY MONITORING METHODS : Based on CPCB Methods /NAAQ-18.11.09 Gazette Notifications INSTRUMENTS: RDS/FPS/COMBO, GC. AAS, Spectrophotometer
Sample Details : AAQ Sample Reference: EIL/APL/10/26/AAQ: 7-12	Sample Collection Date: 14 & 15/10/26 Sample Reporting Date: 21/10/26

WEEK – II

SAMPLING SITE	UNIT	NEAR Gate No. 02	Near ETP Area	NEAR RMG Area	NEAR Gate no.02	Near ETP Area	NEAR RMG Area	Stds* Annual NAAQ
Sampling Code	--	AAQ – 7	AAQ – 8	AAQ – 9	AAQ – 10	AAQ – 11	AAQ – 12	--
Sampling Date	--	14/10/26 T0 15/10/26	14/10/26 T0 15/10/26	14/10/26 T0 15/10/26	15/10/26 T0 16/10/26	15/10/26 T0 16/10/26	15/10/26 T0 16/10/26	--
Sampling Duration	--	24 Hours	24 Hours	24 Hours	24 Hours	24 Hours	24 Hours	--
Product	--	Paint	Paint	Paint	Paint	Paint	Paint	--
Average Operating Hours	--	3 Shift	3 Shift	3 Shift	3 Shift	3 Shift	3 Shift	--
Weather	--	Normal	Normal	Normal	Normal	Normal	Normal	--
Wind Direction	--	W – E	W – E	W – E	W – E	W – E	W – E	--
Ambient Temperature	°K	302	302	302	302	302	302	--
Particulate Matters -PM10	$\mu g/m^3$	266	282	249	272	253	267	< 60
Particulate Matters -PM2.5	$\mu g/m^3$	162	151	172	150	166	180	< 40
Sulphur Di Oxide (SO2)	$\mu g/m^3$	33	30	38	28	37	42	< 50
Nitrogen Di Oxide (NO2)	$\mu g/m^3$	27	22	20	30	24	28	<40
Ozone as O3	$\mu g/m^3$	11	14	09	12	16	13	< 100**
Lead as Pb	$\mu g/m^3$	BDL	BDL	BDL	BDL	BDL	BDL	< 0.5
Carbon Monoxide as CO	mg/m^3	<1	<1	<1	<1	<1	<1	< 2**
Ammonia as NH3	$\mu g/m^3$	10	14	08	06	07	12	<100
Benzene as C6H6	$\mu g/m^3$	BDL	BDL	BDL	BDL	BDL	BDL	< 05
Benzene (a)Pyrene	ng/m^3	BDL	BDL	BDL	BDL	BDL	BDL	< 01
Arsenic as As	ng/m^3	BDL	BDL	BDL	BDL	BDL	BDL	<06
Nickel as Ni	ng/m^3	BDL	BDL	BDL	BDL	BDL	BDL	<20

*EPR-1986/ Schedule VII/NAAQ/Page561/Annual,** 8 Hours. BDL. <0.25,

Checked By
R.P. Marwah

EIL/Lab-In-Charge
Dr. Vipul Kumar

Greater Noida

N.B.:-
- The Sample/Samples received shall be destroyed after 2 weeks unless specified otherwise.
- The Result indicated only refer to the tested samples.
- The Certificate shall not be used in any media or as evidence in the court of law.

Off. & Lab : 138-139, Udyog Kendra-II Extn, Eco Tech-III, Greater Noida-201 306
: 9810098664, 9810725666, 9910233668
: vipul_kumar4@rediffmail.com | environternationalec@gmail.com

ISO/IEC-17021 CB

— ENVIRO-INTERNATIONAL —

NABL, UPPCB-HO/600/CC/89/2009-10/2023 & ISO : 9001 : 2015, ISO : 14001 : 2015,
ISO : 45001 : 2018 Certified Environmental Laboratory
PAN: AAAFE9844N | GSTIN: 09AAAFE9844N1ZT

27 YEARS SERVICES

TEST REPORT

ISSUED TO: M/s. ASIAN PAINTS LIMITED, A1B2, UPSIDC INDUSTRIAL AREA, KASNA VILLAGE, Gr. NOIDA, G.B. NAGAR – 203207 (UP) INDIA.	SUBJECT : AMBIENT AIR QUALITY MONITORING METHODS : Based on CPCB Methods /NAAQ-18.11.09 Gazette Notifications INSTRUMENTS: RDS/FPS/COMBO, GC. AAS, Spectrophotometer
Sample Details : AAQ Sample Reference: EIL/APL/10/26 /AAQ: 13 – 18	Sample Collection Date: 21 & 22/10/26 Sample Reporting Date: 28/10/26

WEEK – III

SAMPLING SITE	UNIT	NEAR Gate No. 02	Near ETP Area	NEAR RMG Area	NEAR Gate no.02	Near ETP Area	NEAR RMG Area	Stds* Annual NAAQ
Sampling Code	--	AAQ – 13	AAQ – 14	AAQ – 15	AAQ – 16	AAQ – 17	AAQ – 18	--
Sampling Date	--	21/10/26 T0 22/10/26	21/10/26 T0 22/10/26	21/10/26 T0 22/10/26	22/10/26 T0 23/10/26	22/10/26 T0 23/10/26	22/10/26 T0 23/10/26	--
Sampling Duration	--	24 Hours	24 Hours	24 Hours	24 Hours	24 Hours	24 Hours	--
Product	--	Paint	Paint	Paint	Paint	Paint	Paint	--
Average Operating Hours	--	3 Shift	3 Shift	3 Shift	3 Shift	3 Shift	3 Shift	--
Weather	--	Normal	Normal	Normal	Normal	Normal	Normal	--
Wind Direction	--	W – E	W – E	W – E	W – E	W – E	W – E	--
Ambient Temperature	°K	300	300	300	300	300	300	--
Particulate Matters (PM10)	$\mu g/m^3$	231	240	246	234	227	258	< 60
Particulate Matters (PM2.5)	$\mu g/m^3$	126	144	153	137	156	145	< 40
Sulphur Di Oxide (SO2)	$\mu g/m^3$	43	35	48	39	42	40	< 50
Nitrogen Di Oxide (NO2)	$\mu g/m^3$	23	28	22	24	26	21	<40
Ozone as O3	$\mu g/m^3$	16	18	12	18	13	10	< 100**
Lead as Pb	$\mu g/m^3$	BDL	BDL	BDL	BDL	BDL	BDL	< 0.5
Carbon Monoxide as CO	mg/m^3	<1	<1	<1	<1	<1	<1	< 2**
Ammonia as NH3	$\mu g/m^3$	05	09	04	09	03	10	<100
Benzene as C6H6	$\mu g/m^3$	BDL	BDL	BDL	BDL	BDL	BDL	< 05
Benzene (a)Pyrene	ng/m^3	BDL	BDL	BDL	BDL	BDL	BDL	< 01
Arsenic as As	ng/m^3	BDL	BDL	BDL	BDL	BDL	BDL	<06
Nickel as Ni	ng/m^3	BDL	BDL	BDL	BDL	BDL	BDL	<20

*EPR-1986/ Schedule VII/NAAQ/Page561/Annual,** 8 Hours, BDL <0.25,

Checked By

R.P. Marwah

EIL/Lab-In-Charge

Dr. Vipul Kumar

Greater Noida

N.B.:-

- The Sample/Samples received shall be destroyed after 2 weeks unless specified otherwise.
- The Result indicated only refer to the tested samples.
- The Certificate shall not be used in any media or as evidence in the court of law.

Off. & Lab : 138-139, Udyog Kendra-II Extn, Eco Tech-III, Greater Noida-201 306
: 9810098664, 9810725666, 9910233668
: vipul_kumar4@rediffmail.com | environternationalec@gmail.com

ISO/IEC-17021 CB

— ENVIRO-INTERNATIONAL —

NABL, UPPCB-HO/600/CC/89/2009-10/2023 & ISO : 9001 : 2015, ISO : 14001 : 2015,
ISO : 45001 : 2018 Certified Environmental Laboratory
PAN: AAAFE9844N | GSTIN: 09AAAFE9844N1ZT

27 YEARS SERVICE

TEST REPORT

ISSUED TO: M/s. ASIAN PAINTS LIMITED. A1B2, UPSIDC INDUSTRIAL AREA, KASNA VILLAGE, G. NOIDA, G.B. NAGAR – 203207 (UP) INDIA.	SUBJECT : AMBIENT AIR QUALITY MONITORING METHODS : Based on CPCB Methods /NAAQ-18.11.09 Gazette Notifications INSTRUMENTS: RDS/FPS/COMBO, GC, AAS, Spectrophotometer
Sample Details : AAQ Sample Reference: EIL/APL/10/26 /AAQ: 19 – 24	Sample Collection Date: 28 & 29/10/26 Sample Reporting Date: 31/10/26

WEEK – IV

SAMPLING SITE	UNIT	NEAR Gate No. 02	Near ETP Area	NEAR RMG Area	NEAR Gate no.02	Near ETP Area	NEAR RMG Area	Stds* Annual NAAQ
Sampling Code	--	AAQ – 19	AAQ – 20	AAQ – 21	AAQ –22	AAQ – 23	AAQ – 24	--
Sampling Date	--	28/10/26 TO 29/10/26	28/10/26 TO 29/10/26	28/10/26 TO 29/10/26	29/10/26 TO 30/10/26	29/10/26 TO 30/10/26	29/10/26 TO 30/10/26	--
Sampling Duration	--	24 Hours	24 Hours	24 Hours	24 Hours	24 Hours	24 Hours	--
Product	--	Paint	Paint	Paint	Paint	Paint	Paint	--
Average Operating Hours	--	3 Shift	3 Shift	3 Shift	3 Shift	3 Shift	3 Shift	--
Weather	--	Normal	Normal	Normal	Normal	Normal	Normal	--
Wind Direction	--	W – E	W – E	W – E	W – E	W – E	W – E	--
Ambient Temperature	°K	301	301	301	301	301	301	--
Particulate Matters PM10	µg/m³	194	190	202	223	247	224	< 60
Particulate Matters PM2.5	µg/m³	112	121	109	129	115	126	< 40
Sulphur Di Oxide (SO2)	µg/m³	30	25	26	32	29	27	<50
Nitrogen Di Oxide (NO2)	µg/m³	25	18	24	20	17	21	<40
Ozone as O3	µg/m³	08	10	13	06	12	16	< 100**
Lead as Pb	µg/m³	BDL	BDL	BDL	BDL	BDL	BDL	< 0.5
Carbon Monoxide as CO	mg/m³	<1	<1	<1	<1	<1	<1	< 2**
Ammonia as NH3	µg/m³	12	10	14	10	15	08	<100
Benzene as C6H6	µg/m³	BDL	BDL	BDL	BDL	BDL	BDL	< 05
Benzeno (a)Pyrene	ng/m³	BDL	BDL	BDL	BDL	BDL	BDL	< 01
Arsenic as As	ng/m³	BDL	BDL	BDL	BDL	BDL	BDL	<06
Nickel as Ni	ng/m³	BDL	BDL	BDL	BDL	BDL	BDL	<20

*EPR-1986/ Schedule VII/NAAQ/Page561/Annual.** 8 Hours. BDL. <0.25,

Checked By
R.P. Marwah

EIL/Lab-In-Charge
Dr. Vipul Kumar

ENVIRO INTERNATIONAL Greater Noida

N.B.:-
- The Sample/Samples received shall be destroyed after 2 weeks unless specified otherwise.
- The Result indicated only refer to the tested samples.
- The Certificate shall not be used in any media or as evidence in the court of law.

Off. & Lab :138-139, Udyog Kendra-II Extn, Eco Tech-III, Greater Noida-201 306
:9810098664, 9810725666, 9910233668
:vipul_kumar4@rediffmail.com | envirointernationalec@gmail.com

IAF MLA UAF ISO/IEC-17021 CB

— ENVIRO-INTERNATIONAL —

NABL, UPPCB-HO/600/CC/89/2009-10/2023 & ISO : 9001 : 2015, ISO : 14001 : 2015,
ISO : 45001 : 2018 Certified Environmental Laboratory
PAN: AAAFE9844N | GSTIN: 09AAAFE9844N1ZT

27 YEARS SERVICE

TEST REPORT

ISSUED TO: M/s. ASIAN PAINTS LIMITED. A1B2, UPSIDC INDUSTRIAL AREA, KASNA VILLAGE, Gr. NOIDA, G.B. NAGAR – 203207 (UP) INDIA,	SUBJECT : AMBIENT AIR QUALITY MONITORING METHODS : Based on CPCB Methods /NAAQ-18.11.09 Gazette Notifications INSTRUMENTS: RDS/FPS/COMBO, GC, AAS, Spectrophotometer
Sample Details : AAQ Sample Reference: EIL/APL/10/26//W AAQ: 1-2	Sample Collection Date: 05 & 06/10/26 Sample Reporting Date: 12//10/26

WEEK – I

SAMPLING SITE	UNIT	Paint House Roof	Paint House Roof	Stds* Annual NAAQ
Sampling Code	--	AAQ – 1	AAQ – 2	--
Sampling Date	--	05/10/26 To 06/10/26	06/10/26 To 07/10/26	--
Sampling Duration	--	24 Hours	24 Hours	--
Product	--	Paint	Paint	--
Average Operating Hours	--	3 Shift	3 Shift	--
Weather	--	Normal	Normal	--
Wind Direction	--	S-W	S-W	--
Ambient Temperature	°K	303	303	--
Particulate Matters <PM10	µg/m³	290	275	< 60
Particulate Matters <PM2.5	µg/m³	182	189	< 40
Sulphur Di Oxide (SO2)	µg/m³	44	48	< 50
Nitrogen Di Oxide (NO2)	µg/m³	32	28	<40
Ozone as O3	µg/m³	22	19	< 100**
Lead as Pb	µg/m³	BDL	BDL	< 0.5
Carbon Monoxide as CO	mg/m³	<1	<1	< 2**
Ammonia as NH3	µg/m³	10	07	<100
Benzene as C6H6	µg/m³	BDL	BDL	< 05
Benzene (a)Pyrene	ng/m³	BDL	BDL	< 01
Arsenic as As	ng/m³	BDL	BDL	<06
Nickel as Ni	ng/m³	BDL	BDL	<20

*EPR-1986/ Schedule VII/NAAQ/Page-561/ Annual.** 8 Hours. BDL: <0.25.

Checked By

R.P. Mau...

EIL/Lab-In-Charge
Dr. Vipul Kumar

ENVIRO INTERNATIONAL Greater Noida

N.B.:-
- The Sample/Samples received shall be destroyed after 2 weeks unless specified otherwise.
- The Result indicated only refer to the tested samples.
- The Certificate shall not be used in any media or as evidence in the court of law.

Off. & Lab : 138-139, Udyog Kendra-II Extn, Eco Tech-III, Greater Noida-201 306
: 9810098664, 9810725666, 9910233668
: vipul_kumar4@rediffmail.com | environternationalec@gmail.com

IAF MEMBER OF MULTILATERAL RECOGNITION ARRANGEMENT
UAF UNITED ACCREDITATION FOUNDATION
ISO/IEC-17021 CB

— ENVIRO-INTERNATIONAL —

NABL, UPPCB-HO/600/CC/89/2009-10/2023 & ISO : 9001 : 2015, ISO : 14001 : 2015,
ISO : 45001 : 2018 Certified Environmental Laboratory
PAN: AAAFE9844N | GSTIN: 09AAAFE9844N1ZT

27 YEARS SERVICES

TEST REPORT

ISSUED TO: M/s. ASIAN PAINTS LIMITED. A1B2, UPSIDC INDUSTRIAL AREA, KASNA VILLAGE, Gr. NOIDA, G.B. NAGAR – 203207 (UP) INDIA,	SUBJECT : AMBIENT AIR QUALITY MONITORING METHODS : Based on CPCB Methods /NAAQ-18.11.09 Gazette Notifications INSTRUMENTS: RDS/FPS/COMBO, GC. AAS, Spectrophotometer
Sample Details : AAQ Sample Reference: EIL/APL/10/26/W AAQ: 3-4	Sample Collection Date: 12 & 13/10/26 Sample Reporting Date: 19//10/26

WEEK – II

SAMPLING SITE	UNIT	Paint House Roof	Paint House Roof	Stds* Annual NAAQ
Sampling Code	--	AAQ – 3	AAQ – 4	--
Sampling Date	--	12/10/26 To 13/10/26	13/10/26 To 14/10/26	--
Sampling Duration	--	24 Hours	24 Hours	--
Product	--	Paint	Paint	--
Average Operating Hours	--	3 Shift	3 Shift	--
Weather	--	Normal	Normal	--
Wind Direction	--	W – E	W – E	--
Ambient Temperature	°K	302	302	--
Particulate Matters <PM10	$\mu g/m^3$	285	312	< 60
Particulate Matters <PM2.5	$\mu g/m^3$	180	206	< 40
Sulphur Di Oxide (SO2)	$\mu g/m^3$	57	45	< 50
Nitrogen Di Oxide (NO2)	$\mu g/m^3$	30	24	<40
Ozone as O3	$\mu g/m^3$	13	11	< 100**
Lead as Pb	$\mu g/m^3$	BDL	BDL	< 0.5
Carbon Monoxide as CO	mg/m^3	<1	<1	< 2**
Ammonia as NH3	$\mu g/m^3$	12	08	<100
Benzene as C6H6	$\mu g/m^3$	BDL	BDL	< 05
Benzeno (α)Pyrene	ng/m^3	BDL	BDL	< 01
Arsenic as As	ng/m^3	BDL	BDL	<06
Nickel as Ni	ng/m^3	BDL	BDL	<20

*EPR-1986/ Schedule VII/NAAQ/Page561/Annual.** 8 Hours, BDL. <0.25,

Checked By
R.P. Marwah

EIL/Lab-In-Charge
Dr. Vipul Kumar

ENVIRO-INTERNATIONAL Greater Noida

N.B.:-
- The Sample/Samples received shall be destroyed after 2 weeks unless specified otherwise.
- The Result indicated only refer to the tested samples.
- The Certificate shall not be used in any media or as evidence in the court of law.

Off. & Lab :138-139, Udyog Kendra-II Extn, Eco Tech-III, Greater Noida-201 306
:9810098664, 9810725666, 9910233668
:vipul_kumar4@rediffmail.com | environternationalec@gmail.com

IAF MLA | UAF United Accreditation Foundation
ISO/IEC-17021 CB

— ENVIRO-INTERNATIONAL —

NABL, UPPCB-HO/600/CC/89/2009-10/2023 & ISO : 9001 : 2015, ISO : 14001 : 2015,
ISO : 45001 : 2018 Certified Environmental Laboratory
PAN: AAAFE9844N | GSTIN: 09AAAFE9844N1ZT

27 YEARS SERVICES

TEST REPORT

ISSUED TO:	
M/s. ASIAN PAINTS LIMITED, A1B2, UPSIDC INDUSTRIAL AREA, KASNA VILLAGE, Gr. NOIDA, G.B. NAGAR – 203207 (UP) INDIA,	SUBJECT : AMBIENT AIR QUALITY MONITORING METHODS : Based on CPCB Methods /NAAQ-18.11.09 Gazette Notifications INSTRUMENTS: RDS/FPS/COMBO, GC. AAS, Spectrophotometer
Sample Details : AAQ Sample Reference: EIL/APL/10/26/W AAQ: 5-6	Sample Collection Date: 19 & 20/10/26 Sample Reporting Date: 26//10/26

WEEK – III

SAMPLING SITE	UNIT	Paint House Roof	Paint House Roof	Stds* Annual NAAQ
Sampling Code	--	AAQ – 5	AAQ – 6	--
Sampling Date	--	19/10/26 To 20/10/26	20/10/26 To 21/10/26	--
Sampling Duration	--	24 Hours	24 Hours	--
Product	--	Paint	Paint	--
Average Operating Hours	--	3 Shift	3 Shift	--
Weather	--	Normal	Normal	--
Wind Direction	--	W – E	W – E	--
Ambient Temperature	°K	303	303	--
Particulate Matters PM10	µg/m³	294	282	< 60
Particulate Matters PM2.5	µg/m³	175	160	< 40
Sulphur Di Oxide (SO2)	µg/m³	40	46	< 50
Nitrogen Di Oxide (NO2)	µg/m³	33	28	<40
Ozone as O3	µg/m³	15	11	< 100**
Lead as Pb	µg/m³	BDL	BDL	< 0.5
Carbon Monoxide as CO	mg/m³	<1	<1	< 2**
Ammonia as NH3	µg/m³	06	09	<100
Benzene as C6H6	µg/m³	BDL	BDL	< 05
Benzeno (a)Pyrene	ng/m³	BDL	BDL	< 01
Arsenic as As	ng/m³	BDL	BDL	<06
Nickel as Ni	ng/m³	BDL	BDL	<20

*EPR-1986/ Schedule VII/NAAQ/Page561/Annual.** 8 Hours, BDL <0.25,

Checked By
R.P. Marwah

EIL/Lab-In-Charge
Dr. Vipul Kumar

N.B.:-
- The Sample/Samples received shall be destroyed after 2 weeks unless specified otherwise.
- The Result indicated only refer to the tested samples.
- The Certificate shall not be used in any media or as evidence in the court of law.

Off. & Lab : 138-139, Udyog Kendra-II Extn, Eco Tech-III, Greater Noida-201 306
: 9810098664, 9810725666, 9910233668
: vipul_kumar4@rediffmail.com | environternationalec@gmail.com

ISO/IEC-17021 CB

— ENVIRO-INTERNATIONAL —

NABL, UPPCB-HO/600/CC/89/2009-10/2023 & ISO : 9001 : 2015, ISO : 14001 : 2015,
ISO : 45001 : 2018 Certified Environmental Laboratory
PAN: AAAFE9844N | GSTIN: 09AAAFE9844N1ZT

27 YEARS SERVICE

TEST REPORT

ISSUED TO:	SUBJECT : AMBIENT AIR QUALITY MONITORING METHODS : Based on CPCB Methods /NAAQ-18.11.09 Gazette Notifications INSTRUMENTS: RDS/FPS/COMBO, GC, AAS, Spectrophotometer
M/s. ASIAN PAINTS LIMITED. A1B2, UPSIDC INDUSTRIAL AREA, KASNA VILLAGE, GT. NOIDA, G.B. NAGAR – 203207 (UP) INDIA,	
Sample Details : AAQ Sample Reference: EIL/APL/10/26/W AAQ: 7-8	Sample Collection Date: 26 & 27/10/26 Sample Reporting Date: 30//10/26

WEEK – IV

SAMPLING SITE	UNIT	Paint House Roof	Paint House Roof	Stds* Annual NAAQ
Sampling Code	--	AAQ – 7	AAQ – 8	--
Sampling Date	--	26/10/26 To 27/10/26	27/10/26 To 28/10/26	--
Sampling Duration	--	24 Hours	24 Hours	--
Product	--	Paint	Paint	--
Average Operating Hours	--	3 Shift	3 Shift	--
Weather	--	Normal	Normal	--
Wind Direction	--	W – E	W – E	--
Ambient Temperature	°K	300	300	--
Particulate Matters - PM10	$\mu g/m^3$	264	293	< 60
Particulate Matters -PM2.5	$\mu g/m^3$	169	188	< 40
Sulphur Di Oxide (SO2)	$\mu g/m^3$	40	37	< 50
Nitrogen Di Oxide (NO2)	$\mu g/m^3$	28	24	<40
Ozone as O3	$\mu g/m^3$	09	10	< 100**
Lead as Pb	$\mu g/m^3$	BDL	BDL	< 0.5
Carbon Monoxide as CO	mg/m^3	<1	<1	< 2**
Ammonia as NH3	$\mu g/m^3$	09	12	<100
Benzene as C6H6	$\mu g/m^3$	BDL	BDL	< 05
Benzene (a)Pyrene	ng/m^3	BDL	BDL	< 01
Arsenic as As	ng/m^3	BDL	BDL	<06
Nickel as Ni	ng/m^3	BDL	BDL	<20

*EPR-1986/ Schedule VII/NAAQ/Page561/Annual,** 8 Hours. BDL: <0.25,

Checked By
R.P. Marwah

EIL/Lab-In-Charge
Dr. Vipul Kumar

ENVIRO INTERNATIONAL Greater Noida

N.B.:-
- The Sample/Samples received shall be destroyed after 2 weeks unless specified otherwise.
- The Result indicated only refer to the tested samples.
- The Certificate shall not be used in any media or as evidence in the court of law.

Off. & Lab : 138-139, Udyog Kendra-II Extn, Eco Tech-III, Greater Noida-201 306
: 9810098664, 9810725666, 9910233668
: vipul_kumar4@rediffmail.com | environternationalec@gmail.com

MEMBER OF MULTILATERAL RECOGNITION ARRANGEMENT IAF
UNITED ACCREDITATION FOUNDATION UAF
ISO/IEC-17021 CB

— ENVIRO-INTERNATIONAL —

NABL, UPPCB-HO/600/CC/89/2009-10/2023 & ISO : 9001 : 2015, ISO : 14001 : 2015,
ISO : 45001 : 2018 Certified Environmental Laboratory
PAN: AAAFE9844N | GSTIN: 09AAAFE9844N1ZT

27 YEARS SERVICES

TEST REPORT

ISSUED TO:
M/s. ASIAN PAINTS LIMITED.
A1B2, UPSIDC INDUSTRIAL AREA, KASNA VILLAGE,
G. NOIDA, G.B. NAGAR - 203207 (UP) INDIA.

SUBJECT : STACK EMISSION MONITORING & ANALYSIS
PRINCIPLE & METHODS: Based on IS : Code 4167/5182/APHA
INSTRUMENTS : Stack Sampler, APM 602/APM 620/ESS 100, Spectrophotometer

Sample Details : STACK
Sample Reference: EIL/APL/10/26/S-16

Sample Collection Date: 27/10/26
Sample Reporting Date: 30/10/26

Stack Attached To	Unit	G.G. Set – 01 1765 KVA (1.5 MW)	Methods	Standard*
Stack No.	--	SG-01	--	--
Source of Emission	--	PNG	--	--
Fuel Consumption	--	400 Scm./Hr.	--	--
Stack Identification	--	M.S.	--	--
Stack Height [Ground]	Meter	30.50	--	--
Stack Shape	--	Circular	--	--
Stack Diameter	Mm	400	--	--
Product	--	Paint	--	--
Average Operating Hrs.	--	3 Shift	--	--
Stack Temperature	°K	409	--	--
Ambient Temperature	°K	303	--	--
Sampling Duration	Seconds	3600	--	--
Flow Rate of SPM	LPM	15.00	--	--
Flow Rate of Gases	LPM	1.0	--	--
Velocity	m/sec.	10.8	--	--
Quantity of Emission	$Nm^3/Hr.$	3558.02	IS 11255/CPCB	--
Particulate Matters	mg/Nm^3	29.53	IS 11255/CPCB	0 – 50
Oxide of Nitrogen as NOx	Ppmv	66	IS 11255/CPCB	0–650
Sulphur Di Oxide as SO_2	mg/Nm^3	20	IS 11255/CPCB	Not Specified
Carbon Mono Oxide	mg/Nm^3	05	IS 11255/CPCB	0 – 100
NMHC	mg/Nm^3	BDL	IS 11255/CPCB	--

*As per (1) Environmental [Protection] Rules, 1986, GSR 489 {E} F.No. Q-15017/24/2002-CPWDated 9th July, 2002, Issued by: Ministry of Environment and Forests- New Delhi [New Notification for More Than 800 KVA Diesel Engines. (2) Sampling & Methods Base on above said new Notification. (3) Sampling duration Load was 85 %

Checked By
R.P. Marwah

EIL./Lab-In-Charge
Dr. Vipul Kumar

ENVIRO INTERNATIONAL Greater Noida

N.B.:-
- The Sample/Samples received shall be destroyed after 2 weeks unless specified otherwise.
- The Result indicated only refer to the tested samples.
- The Certificate shall not be used in any media or as evidence in the court of law.

Off. & Lab : 138-139, Udyog Kendra-II Extn, Eco Tech-III, Greater Noida-201 306
: 9810098664, 9810725666, 9910233668
: vipul_kumar4@rediffmail.com | environternationalec@gmail.com

MEMBER OF MULTILATERAL RECOGNITION ARRANGEMENT IAF
UNITED ACCREDITATION FOUNDATION UAF
ISO/IEC-17021 CB

— ENVIRO-INTERNATIONAL —

NABL, UPPCB-HO/600/CC/89/2009-10/2023 & ISO : 9001 : 2015, ISO : 14001 : 2015,
ISO : 45001 : 2018 Certified Environmental Laboratory
PAN: AAAFE9844N | GSTIN: 09AAAFE9844N1ZT

27 YEARS SERVICES

TEST REPORT

ISSUED TO:
M/s. ASIAN PAINTS LIMITED,
A1B2, UPSIDC INDUSTRIAL AREA, KASNA VILLAGE,
G.T. NOIDA, G.B. NAGAR - 203207 (UP) INDIA,

SUBJECT : STACK EMISSION MONITORING & ANALYSIS
PRINCIPLE & METHODS: Based on IS : Code 4167/5182/APHA
INSTRUMENTS : Stack Sampler, APM 602/APM 620/ESS 100, Spectrophotometer

Sample Details : STACK
Sample Reference: EIL/API/10/26/S-17

Sample Collection Date: 27/10/26
Sample Reporting Date: 30/10/26

Stack Attached To	Unit	G.G. Set – 02 1765 KVA (1.5 MW)	Methods	Standard*
Stack No.	--	SG-02	--	--
Source of Emission	--	PNG	--	--
Fuel Consumption	--	400 Scm./Hr.	--	--
Stack Identification	--	M.S.	--	--
Stack Height [Ground]	meter	30.50	--	--
Stack Shape	--	Circular	--	--
Stack Diameter	mm	400	--	--
Product	--	Paint	--	--
Average Operating Hrs.	--	3 Shift	--	--
Stack Temperature	°K	398	--	--
Ambient Temperature	°K	303	--	--
Sampling Duration	Seconds	3600	--	--
Flow Rate of SPM	LPM	15.00	--	--
Flow Rate of Gases	LPM	1.0	--	--
Velocity	m/sec.	11.2	--	--
Quantity of Emission	$Nm^3/Hr.$	3791.78	IS 11255/CPCB	--
Particulate Matters	mg/Nm^3	30.0	IS 11255/CPCB	0 – 50
Oxide of Nitrogen as NOx	ppmv	82	IS 11255/CPCB	0–650
Sulphur Di Oxide as SO_2	mg/Nm^3	09	IS 11255/CPCB	Not Specified
Carbon Mono Oxide	mg/Nm^3	03	IS 11255/CPCB	0 – 100
S.M.H.C.	mg/Nm^3	BDL	IS 11255/CPCB	--

N.B.: (1)* Environmental [Protection] Rules, 1986, GSR 489 {E} F.No. Q-15017/24/2002-CPWDated 9th July, 2002, Issued by: Ministry of Environment and Forests- New Delhi [New Notification for More Than 800 KVA Diesel Engines. (2) Sampling & Methods Base on above said new Notification. (3) Sampling duration Load was 85 %

Checked By
R.P. Marwah

EIL/Lab-In-Charge
Dr. Vipul Kumar

Greater Noida

N.B.:-
- The Sample/Samples received shall be destroyed after 2 weeks unless specified otherwise.
- The Result indicated only refer to the tested samples.
- The Certificate shall not be used in any media or as evidence in the court of law.

Off. & Lab : 138-139, Udyog Kendra-II Extn, Eco Tech-III, Greater Noida-201 306
: 9810098664, 9810725666, 9910233668
: vipul_kumar4@rediffmail.com | environternationalec@gmail.com

ISO/IEC-17021 CB

— ENVIRO-INTERNATIONAL —

NABL, UPPCB-HO/600/CC/89/2009-10/2023 & ISO : 9001 : 2015, ISO : 14001 : 2015,
ISO : 45001 : 2018 Certified Environmental Laboratory
PAN: AAAFE9844N | GSTIN: 09AAAFE9844N1ZT

27 YEARS SERVICES

TEST REPORT

ISSUED TO: M/s. ASIAN PAINTS LIMITED. A1B/1, UPSIDC INDUSTRIAL AREA, KASNA VILLAGE, G. NOIDA, G.B. NAGAR – 203207 (UP) INDIA,	SUBJECT : STACK EMISSION MONITORING & ANALYSIS PRINCIPLE & METHODS: Based on IS : Code 4167/5182/APHA INSTRUMENTS : Stack Sampler, APM 602/APM 620/ESS 100, Spectrophotometer
Sample Details : STACK Sample Reference: EIL/APL/10/26/S-18	Sample Collection Date: 27/10/26 Sample Reporting Date: 30/10/26

Stack Attached To	Unit	G.G. Set – 03 (315 KVA)	Methods	Standard*
Stack No.	--	SG-03	--	--
Source of Emission	--	PNG	--	--
Fuel Consumption	--	71Scm /Hr	--	--
Stack Identification	--	M.S.	--	--
Stack Height [Ground]	meter	10.90	--	--
Stack Shape	--	Circular	--	--
Stack Diameter	mm	200	--	--
Product	--	Paint	--	--
Average Operating Hrs.	--	3 Shift	--	--
Stack Temperature	°K	404	--	--
Ambient Temperature	°K	303	--	--
Sampling Duration	Seconds	3600	--	--
Flow Rate of SPM	LPM	15.00	--	--
Flow Rate of Gases	LPM	1.0	--	--
Velocity	m/sec.	7.8	--	--
Quantity of Emission	$Nm^3/Hr.$	650.37	IS 11255/CPCB	--
Particulate Matters	mg/Nm^3	24	IS 11255/CPCB	0 – 50
Oxide of Nitrogen as NOx	ppmv	66	IS 11255/CPCB	0–650
Sulphur Di Oxide as SO_2	mg/Nm^3	13	IS 11255/CPCB	Not Specified
Carbon Mono Oxide	mg/Nm^3	03	IS 11255/CPCB	0 – 100
NMHC	mg/Nm^3	BDL	IS 11255/CPCB	--

N.B.:-(1)* Environmental [Protection] Rules, 1986, GSR 489 {E] F.No. Q-15017/24/2002-CPWDated 9th July, 2002, Issued by: Ministry of Environment and Forests- New Delhi [New Notification for More Than 800 KVA Diesel Engines. (2) Sampling & Methods Base on above said new Notification. (3) Sampling duration Load was 85 %

Checked By
R.P. Marwah

EIL/Lab-In-Charge
Dr. Vipul Kumar

Greater Noida

N.B.:-
- The Sample/Samples received shall be destroyed after 2 weeks unless specified otherwise.
- The Result indicated only refer to the tested samples.
- The Certificate shall not be used in any media or as evidence in the court of law.

Off. & Lab : 138-139, Udyog Kendra-II Extn, Eco Tech-III, Greater Noida-201 306
9810098664, 9810725666, 9910233668
vipul_kumar4@rediffmail.com | environternationalec@gmail.com

ISO/IEC-17021 CB

— ENVIRO-INTERNATIONAL —

NABL, UPPCB-HO/600/CC/89/2009-10/2023 & ISO : 9001 : 2015, ISO : 14001 : 2015,
ISO : 45001 : 2018 Certified Environmental Laboratory
PAN: AAAFE9844N | GSTIN: 09AAAFE9844N1ZT

TEST REPORT

ISSUED TO:
M/s. ASIAN PAINTS LIMITED.
A182, UPSIDC INDUSTRIAL AREA, KASNA VILLAGE,
DIST. NOIDA, G.B. NAGAR – 203207 (UP) INDIA,

SUBJECT : STACK EMISSION MONITORING & ANALYSIS
PRINCIPLE & METHODS: Based on IS: Code 4167/5182/APHA
INSTRUMENTS : Stack Sampler, APM 602/APM 620/ESS 100,
Spectrophotometer

Sample Details : STACK
Sample Reference: EIL/APL/10/26/S: 9-11

Sample Collection Date: 26/10/26
Sample Reporting Date: 30/10/26

Stack Attached To	Unit	Thermo pack TPK 407 20 Lakh KC	Thermo pack TPK 410 20 Lakh KC	Thermo pack TPK 801 1.0 Lakh KC	Method	Standard
Source of Emission	--	PNG	PNG	PNG	--	--
Stack Height [Ground]	Meter	32.00	32.00	12.00	--	--
Stack Shape	--	Circular	Circular	Circular	--	--
Stack Diameter	Mm	860	810	150	--	--
Product	--	Paint	Paint	Paint	--	--
Average Operating Hours	--	As per requirement	As per requirement	As per requirement	--	--
Stack Temperature	°K	361	384	351	--	--
Ambient Temperature	°K	303	303	303	--	--
Sampling Duration	Second	3600	3600	3600	--	--
Flow Rate of SPM	LPM	14.00	14.00	14.0	--	--
Flow Rate of Gases	LPM	1.0	1.0	1.0	--	--
Velocity	m/sec.	5.2	6.0	4.9	--	--
Quantity of Emission	$Nm^3/Hr.$	8971.84	8633.33	264.52	IS 11255/CPCB	--
Particulate Matters	mg/Nm^3	20.89	25.78	27.54	IS 11255/CPCB	<50
Oxide of Sulphur	mg/Nm^3	18	21	25	IS 11255/CPCB	--
Oxide of Nitrogen	mg/Nm^3	27	32	34	IS 11255/CPCB	--
Carbon Dioxide	mg/kg	-	-	-	IS 11255/CPCB	--
Carbon Mono Oxide	V/v%	0.1	0.2	0.2	IS 11255/CPCB	--
Oxygen	%	17.0	17.6	18.2	IS 11255/CPCB	--
Sulphate Mist	PPM	-	-	-	IS 11255/CPCB	--
Hydro Carbon	PPM	-	-	-	IS 11255/CPCB	--
Ammonia	PPM	-	-	-	IS 11255/CPCB	---
Fluorine	PPM	-	-	-	IS 11255/CPCB	--
Mercaptan	PPM	-	-	-	IS 11255/CPCB	--
Metal Dust as Fe, Zn Cu etc	PPM	-	-	-	IS 11255/CPCB	--

Sampling Done by Mr Shiv Singh & Mr Mahesh.

Checked By

R.P. Marwah

EIL/Lab-In-Charge

Dr. Vipul Kumar

N.B.:-
- The Sample/Samples received shall be destroyed after 2 weeks unless specified otherwise.
- The Result indicated only refer to the tested samples.
- The Certificate shall not be used in any media or as evidence in the court of law.

Off. & Lab : 138-139, Udyog Kendra-II Extn, Eco Tech-III, Greater Noida-201 306
: 9810098664, 9810725666, 9910233668
: vipul_kumar4@rediffmail.com | envirointernationalec@gmail.com

ISO/IEC-17021 CB

— ENVIRO-INTERNATIONAL —

NABL, UPPCB-HO/600/CC/89/2009-10/2023 & ISO : 9001 : 2015, ISO : 14001 : 2015,
ISO : 45001 : 2018 Certified Environmental Laboratory
PAN: AAAFE9844N | GSTIN: 09AAAFE9844N1ZT

27 YEARS SERVICES

TEST REPORT

ISSUED TO:
M/s. ASIAN PAINTS LIMITED.
A1B2, UPSIDC INDUSTRIAL AREA, KASNA VILLAGE,
G. NOIDA, G B NAGAR – 203207 (UP) INDIA,

SUBJECT : STACK EMISSION MONITORING & ANALYSIS
PRINCIPLE & METHODS: Based on IS: Code 4167/5182/APHA
INSTRUMENTS : Stack Sampler, APM 602/APM 620/ESS 100, Spectrophotometer

Sample Details : **STACK**
Sample Reference: EIL/APL/10/26/S: 12-13

Sample Collection Date: 26/10/26
Sample Reporting Date: 30/10/26

Stack Attached To	Unit	Boiler 802 50 kg/Hr	Non IBR Boiler 2x850 kg/Hr	IBR Boiler 4 TPH BOK 404	Method	Standard
Source of Emission	--	PNG	PNG	PNG	--	--
Stack Height (Ground)	Meter	17.00	32	30.50	--	--
Stack Shape	--	Circular	Circular	Circular	--	--
Stack Diameter	Mm	100	500	600	--	--
Product	--	Paint	Paint	Paint	--	--
Average Operating Hours	--	As per requirement	As per requirement	As per requirement	--	--
Stack Temperature	°K	343	Not Done	365	--	--
Ambient Temperature	°K	303	Not Done	303	--	--
Sampling Duration	Second	3600	Not Done	3600	--	--
Flow Rate of SPM	LPM	12.00	Not Done	14.0	--	--
Flow Rate of Gases	LPM	1.0	Not Done	1.0	--	--
Velocity	m/sec.	5.2	Not Done	5.0	--	--
Quantity of Emission	$Nm^3/Hr.$	127.67	Not Done	4153.06	IS 11255/CPCB	--
Particulate Matters	mg/Nm^3	30.2	Not Done	33.8	IS 11255/CPCB	<50
Oxide of Sulphur	mg/Nm^3	18	Not Done	16	IS 11255/CPCB	--
Oxide of Nitrogen	mg/Nm^3	22	Not Done	20	IS 11255/CPCB	--
Carbon Dioxide	mg/kg	-	Not Done	-	IS 11255/CPCB	--
Carbon Mono Oxide	V/v%	0.3	Not Done	0.2	IS 11255/CPCB	--
Oxygen	%	18.1	Not Done	17.2	IS 11255/CPCB	--
Sulphate Mist	PPM	-	Not Done	-	IS 11255/CPCB	--
Hydro Carbon	PPM	-	Not Done	-	IS 11255/CPCB	--
Ammonia	PPM	-	Not Done	-	IS 11255/CPCB	---
Fluorine	PPM	-	Not Done	-	IS 11255/CPCB	--
Mercaption	PPM	-	Not Done	-	IS 11255/CPCB	--
Metal Dust as Fe, Zn,Cu etc	PPM	-	Not Done	-	IS 11255/CPCB	--

Sampling Done by Mr Shiv Singh & Mr Mahesh.

Checked By
R.P. Marwah

EIL/Lab-In-Charge
Dr. Vipul Kumar

N.B.:-
- The Sample/Samples received shall be destroyed after 2 weeks unless specified otherwise.
- The Result indicated only refer to the tested samples.
- The Certificate shall not be used in any media or as evidence in the court of law.

Off. & Lab : 138-139, Udyog Kendra-II Extn, Eco Tech-III, Greater Noida-201 306
9810098664, 9810725666, 9910233668
vipul_kumar4@rediffmail.com | environternationalec@gmail.com

ISO/IEC-17021 CB