





TAMIL NADU POLLUTION CONTROL BOARD
ADVANCED ENVIRONMENTAL LABORATORY, CUDDALORE.
AMBIENT AIR QUALITY SURVEY

Schematic Diagram Showing Location of Sampling

1. Name and address of the Industry : Ms. Asian Paints Ltd,
(Penta Division)
SIPCOT Industrial Complex,
Kudikadu, Cuddalore 607 005.
2. Date of Survey : 30.7.2021
3. Predominant Wind Direction : NE-SW
4. Weather Condition : Clear Sky

N



Meteorological Conditions	
Predominant wind direction	NE-SW
Wind Speed (km/hr)	2.73
Weather condition	Clear Sky
Rain fall(mm)	Nil

Dy. CSO

For Assistant Director (Lab) (a/c),
AEL, TNPCB, Cuddalore.